





GE  **MAX**

Create Codeslist

- After completing job setup select Points/Measurements/Codes
- Select Codes menu and then select +Add



Create Codeslist

- Input Code, Description, and select drawing type

Drawing type

Single point

Line

Square diagonal

Square center

Rectangle base

Rectangle center

Circle 3P

Circle center

CANCEL

New code

MAIN DATA LAYER & COLOR SYMBOL


Code CP

Description Control Point

Drawing type Single point


Feature GIS

GIS Features ✓ Accept



Create Codeslist

- Select Layer & Color menu
- Layer will default to <Default>
 - Select side menu option to change layer or create new layer
- Select Symbol menu and select the symbol you wish to use
- Now select Accept and the new code will be created



Codes & GIS

Comments and suggestions to

academy@geomax-positioning.com

